A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Inspector

Date: Others Present:	
Weather information since the last inspection.	
Date: Inches of Precipitation: Discharges:Y/N	
Location(s) of discharges of sediment or other pollutants from site:	
Location(s) of BMP's that need to be maintained:	
Location(s) of BMP's that failed to operate as designed or were inadequate:	
Location(s) where additional BMP's are needed:	
Corrective action required changes to SWPPP and dates of implementation:	
CERTIFICATION STATEMENT: I certify under penalty of law that this document and all attact prepared under my direction or supervision in accordance with a system designed to assure personnel property gathered and evaluated the information submitted. Based on my inquiry of persons who manage this system, or those persons directly responsible for gathering the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I at there are significant penalties for submitting false information, including the possibility of imprisonment for knowing violations.	that qualified the person or ormation, the am aware that
Karl Dykman	





Berm failure on West side of project at Porter Rd. Requires re-establishment and cleaning of fugitive sediment.









Berm structures operating as intended along Village Dr.









Areas on Village Dr. that require maintenance and remediation. Gutter flow line, Stockpile at intersection at utility connection and North side of site entrance; all presenting sediment pollution movement from project.