A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Inspector

Date:	_ Inspector:	Others Present:	
Weather inform	mation since the last inspection.		
Date:	Inches of Precipitation:	Discharges:	Y/N
Location(s) of	discharges of sediment or other	pollutants from site:	
	BMP's that need to be maintain		
Location(s) of	_	designed or were inaded	quate:
	nere additional BMP's are neede		
			ation:
prepared under personnel proper persons who n information sub there are signi	my direction or supervision in erty gathered and evaluated the innanage this system, or those peromitted is, to the best of my knowle ficant penalties for submitting for knowing violations.	accordance with a syste aformation submitted. Bassons directly responsible edge and belief, true, acc	s document and all attachments were an designed to assure that qualified used on my inquiry of the person or the for gathering the information, the urate, and complete. I am aware that ing the possibility of the fine and

Meteorological reference: Weather Underground data station, KNMLASCR130.





Construction entrance and use by residential traffic from the East neighborhood end of street





Water station from on-site looking South and street-side looking North







Village Dr. on North margin of site looking East. Again on 4.24.24 looking West



Fueling trailer in staging area, take care not to spill fuel when dispensing. NOTE: 5 gallon bucket is open and empty.



Neighborhood spillway delivering storm water and sediment to off-site pond below site grade, East side of construction staging area.



Construction trash trailer in staging area fence-line. Should be emptied (tarp suggested for municipal roadway transport)



Dust control ongoing.