A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Inspector

Date: Inspector:	Others Present:	
Weather information since the	last inspection.	
Date: Inches of Pr	recipitation: Discharges:Y	/N
Location(s) of discharges of sec	diment or other pollutants from site:	
	d to be maintained:	
Location(s) of BMP's that faile	ed to operate as designed or were inadequate	e:
	SMP's are needed:	
Corrective action required chan	nges to SWPPP and dates of implementation	1:
prepared under my direction or personnel property gathered and persons who manage this system information submitted is, to the b there are significant penalties f imprisonment for knowing violation	Γ: I certify under penalty of law that this doc supervision in accordance with a system de evaluated the information submitted. Based m, or those persons directly responsible for sest of my knowledge and belief, true, accurate for submitting false information, including ons.	esigned to assure that qualified on my inquiry of the person or gathering the information, the e, and complete. I am aware that
Karl Dyeman Inspector		









Perimeter berms re-established and reinforced on project North side along Village, streets swept.





Sediment intrusion onto Village from off-site property North of project, flows along Village north side gutter.



Berm break on West side of project releasing sediment and water flow across Porter Rd.