## **A Mountain Construction**

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



## INSPECTION REPORT

Inspector

Date:	_ Inspector:	Others Present:
Weather inform	nation since the last inspection.	
Date:	Inches of Precipitation:	Discharges:Y/N
Location(s) of	discharges of sediment or other poll	utants from site:
Location(s) of I	BMP's that need to be maintained: _	
Location(s) of	BMP's that failed to operate as design	gned or were inadequate:
Corrective action	on required changes to SWPPP and	dates of implementation:
prepared under personnel prope persons who m information substitute are signif- imprisonment for	my direction or supervision in according the gathered and evaluated the informanage this system, or those persons mitted is, to the best of my knowledge ficant penalties for submitting false or knowing violations.	nalty of law that this document and all attachments were rdance with a system designed to assure that qualified nation submitted. Based on my inquiry of the person or directly responsible for gathering the information, the and belief, true, accurate, and complete. I am aware that information, including the possibility of the fine and
Kare Inspector	l Dykman_	







Area of concern from previous rain events: Nunatak at Village. The sediment is maintained within the closed intersection and shows no evidence of escape into drainage system







Area of concern from previous rain events: Coyote Flats at Village Drives. The sediment is maintained within the intersection and shows no evidence of escape into drainage system.

This area is subject to street sweeping operations.