A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Inspector

Date:	_ Inspector:	Others Present:
Weather inform	mation since the last inspection.	
Date:	Inches of Precipitation:	Discharges:Y/N
Location(s) of	discharges of sediment or other poll	utants from site:
Location(s) of	BMP's that need to be maintained:	
Location(s) of	BMP's that failed to operate as designate as designated as	gned or were inadequate:
Corrective acti	ion required changes to SWPPP and	dates of implementation:
prepared under personnel proper persons who n information sub there are signi imprisonment for	my direction or supervision in according and evaluated the informanage this system, or those persons omitted is, to the best of my knowledge ficant penalties for submitting false or knowing violations.	nalty of law that this document and all attachments were rdance with a system designed to assure that qualified nation submitted. Based on my inquiry of the person or directly responsible for gathering the information, the and belief, true, accurate, and complete. I am aware that information, including the possibility of the fine and
Karl Inspector	Dykman	



Significant sediment tracking and deposition on Village Drive



Porter Rd. and Village Dr. containment berm containment BMP's