A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Date: Inspector:	Others Present:
Weather information since the last inspection.	
Date: Inches of Precipitation:	Discharges:Y/N
Location(s) of discharges of sediment or other poll	utants from site:
Location(s) of BMP's that failed to operate as design	gned or were inadequate:
Corrective action required changes to SWPPP and	dates of implementation:
prepared under my direction or supervision in according personnel property gathered and evaluated the informations who manage this system, or those persons information submitted is, to the best of my knowledge there are significant penalties for submitting false imprisonment for knowing violations.	nalty of law that this document and all attachments were redance with a system designed to assure that qualified nation submitted. Based on my inquiry of the person or directly responsible for gathering the information, the and belief, true, accurate, and complete. I am aware that information, including the possibility of the fine and
Karl Dykman Inspector	



VCT in place



Access to site trailer



Erosion control berm along North perimeter



Erosion control berm at South West water tank area