## **A Mountain Construction**

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



## INSPECTION REPORT

Inspector

Date: Ot	hers Present:
Weather information since the last inspection.	
Date: Inches of Precipitation: I	Discharges:Y/N
Location(s) of discharges of sediment or other pollutants from site:	
Location(s) of BMP's that need to be maintained:	
Location(s) of BMP's that failed to operate as designed or were inadequate:	
Location(s) where additional BMP's are needed:	
Corrective action required changes to SWPPP and date	
CERTIFICATION STATEMENT: I certify under penalty prepared under my direction or supervision in accordance personnel property gathered and evaluated the information persons who manage this system, or those persons direction information submitted is, to the best of my knowledge and there are significant penalties for submitting false informations imprisonment for knowing violations.  **Karl Dyleman**	ace with a system designed to assure that qualified on submitted. Based on my inquiry of the person or ectly responsible for gathering the information, the belief, true, accurate, and complete. I am aware that

Utilities Tie-in activities on closed Village Dr.



Maintain containment of stockpiled soil and paving debris on roadway in closed portion





Pick up trash in yard and empty trash trailer.