A Mountain Construction

SWPPP, Tierra Hermosa Subdivision City of Las Cruces, Doña Ana County, NM



INSPECTION REPORT

Inspector

Date:	Inspector:	Others Present:
Weather info	ormation since the last inspection.	
Date:	Inches of Precipitation:	Discharges:Y/N
Location(s)	of discharges of sediment or other po	ollutants from site:
Location(s)	of BMP's that need to be maintained	:
		signed or were inadequate:
Corrective a	ction required changes to SWPPP an	d dates of implementation:
prepared und personnel pro- persons who information s there are sig imprisonment	der my direction or supervision in accoperty gathered and evaluated the informanage this system, or those personal submitted is, to the best of my knowled gnificant penalties for submitting false to knowing violations.	benalty of law that this document and all attachments were cordance with a system designed to assure that qualified ormation submitted. Based on my inquiry of the person or ns directly responsible for gathering the information, the ge and belief, true, accurate, and complete. I am aware that se information, including the possibility of the fine and
Kark Inspector	Dykman	









Construction yard, Note: Gorilla Snott on location with some totes emptied.









Village Dr. utility tie-in and view of site looking South







Water station on Porter and view of berm in place from Porter looking East